

Mold open limit Ejector retracted Interval Cooling Delay Hold Filling Plast.
 Mold full close Nozzle touch < < < < < > ■ Plast.end

PROD. CONT [UP] OPERATION [STOCKER] [INITIAL]

Shot counter
Mode OFF Non-defect 0 shots
The optional value can be set to the number of the production. When resetting, input 0.

Production counter
Mode OFF Non-defect 0 shots 0 units
Achievement 0% 0 25 50 75 100
Remaining 0 shots 0 units
Cavity 1 units Total 0 shots 0 units
Remaining time: 0 hour 0 min

Product end control
Machine stop OFF End warning OFF
Remaining shot count to trigger warning 0 shots